



HOT TUB ANNUAL 30 POINT CHECK SERVICE

Drain spa
Clean headrests
Vac out remaining water
Install new filter (If New Filter Ordered)
Clean Filter (If New Filter Not Ordered)
Check cabinet for damage
Jets - check operation / pressure
Pumps - check for noise / water pressure
Heater - check operation
Check cabinet for signs of water / stains
Suctions - check operation
Light lenses- check for damage / leaks
Hose lines - check for leaks / blockages
Check cover retaining clips
Check operation of other associated extras (Ozone or music systems)
Clean acrylic surface
Rinse spa
Clean / inspect cover
Check cover lift operation
Check shell for damage
Filtration - check settings cycles
Jets - backs / check for leaks
Pumps - check seals
Heater - check seals
Suctions - clean grates
Lights - check operation
Filter unit - check for leaks
Topside - check operation
Check diverters / air controls
Test Ground Fault Circuit Interrupter (GFCI)

NOTE: If there are found to be any defective / damaged parts these will be either replaced / repaired under warranty (if applicable) or after the Technician has consulted the customer to confirm any additional costs.

SPA COVERS / LIFTERS

Spa covers need to be replaced every 3 years (on average) because of the gradual ingress of water / steam which reduces the insulation benefit and makes them heavy to lift / move. At the time of the service a new cover can be delivered (old one disposed of) if you pre-order, or at a later date (delivery charges applicable) if you wish us to check your cover when we visit. Your Spa Lifter will be checked for proper operation.